



On February 27th 2022, the slide was closed after finding that the cement bases under the pillars were splitting and coming apart. A structural engineer was hired and reviewed the structure..

They found the bases and large portions of the deck to be compromised and requiring replacement.

Water Slide

Update

In the mean time, the slide must remain closed until it is repaired, as the salt water and erosion will continue to cause further damage.

Do you have more questions?

Call 780-624-1000

